## FEDERAL ENERGY REGULATORY COMMISSION Office of Energy Projects Division of Dam Safety and Inspections - Headquarters Office 888 First Street, N.E., Routing Code: PJ-13 Washington, D.C. 20426

August 15, 2018

In reply refer to: P-2082, P-14803 NATDAM-OR00559, CA00323, CA00234, CA00325

Mr. Mark A. Sturtevant Managing Director, Hydro Resources PacifiCorp Energy 825 N.E. Multnomah, Suite 1500 Portland, OR 97232

Mr. Mark Bransom Executive Director Klamath River Renewal Corporation 2001 Addison Street, Suite 317 Berkeley, CA 94704

Subject: Request for Approval of Replacement Member of Independent Board of Consultants for the Klamath Project No. 2082 and the Lower Klamath Project No. 14803

Dear Mr. Sturtevant and Bransom:

The current independent Board of Consultants (BOC) for the Klamath Project No. 2082 and the Lower Klamath Project No. 14803 includes Mr. Dan Hertel, P.E., Mr. James E. Borg, P.E., Dr. R. Craig Findlay, Ph.D., P.E., G.E., Dr. MaryLouise Keefe, Ph.D., Mr. Ted Chant, P.Eng., and Mr. Robert D. Muncil, ARM. Mr. Bransom's August 6, 2018, letter indicates that Mr. Muncil is no longer able to serve on the BOC. Also, Mr. Bransom's August 6, 2018 letter requests approval of Mr. Steven A. Coombs as a replacement member of the BOC.

Mr. Coombs is approved as a member of this BOC.

2

If you have any questions regarding this letter, please call me at 202-502-6314.

Sincerely,

David E. Capka, P.E. Director Division of Dam Safety and Inspections

20180815-3008 FERC PDF (Unofficial) 08/15/2018
Document Content(s)
P-2082 and P-14803 Klamath draft.PDF1-2